

Internal damage to the air motor
may result from operating this unit
without a collet body or similiar
retainer tightened on the spindle.

Form Z438
Date 5-97