



# PARTS LIST FOR 1557P DRILL BASE ATTACHMENT

Form Z665  
Date 3-01/A  
Page 1 of 1




Fig. No.	Part No.	Description
1.	601950	Rigid Base—Standard
2.	601951	Wedge—Right Hand
3.	601952	Wedge—Left Hand
4.	601953	Flexible Pad
5.	601954	Vacuum Seal
6.	601955	Mounting Strip
7.	601956	Vented Screw
8.	601957	Mounting Screw (5)*
9.	601958	Nut (2)*
10.	601959	Knurled Adjusting Nut (2)*
11.	601960	Protection Cap (4)*
12.	601961	Wedge Nut—Right Hand (2)*
13.	601962	Wedge Nut—Left Hand (2)*
14.	601963	Roll Pin (2)*
15.	601964	Buckle
16.	601965	Screw (2)*
17.	601966	Keeper Plate (2)*
18.	601967	Safety Belt
19.	601968	Flexible Bolt Assembly (2)*
Not Shown		
	601969	Rigid Base—Zinc
	601970	Wedge—Right Hand Zinc
	601971	Wedge—Left Hand Zinc
	601972	Mounting Strip—Steel

\*Order Quantity As Required

FURNISH CATALOG, SERIAL, AND MODEL NUMBER  
WHEN ORDERING PARTS

# SIoux TOOLS INC.

2901 FLOYD BOULEVARD ■ PO BOX 507 ■ SIOUX CITY, IOWA 51102-0507 USA ■

Printed In U.S.A.