




## PARTS LIST FOR 500 (SPINDLE ADAPTER)

1. 65496 Adapter-Spindle
2. 65497 Washer (2)
3. 09622 Nut



**SIOUX<sup>TM</sup>**  
**TOOLS INC.**

2901 FLOYD BOULEVARD ■ PO BOX 507 ■ SIOUX CITY, IOWA 51102-0507 USA ■