




PARTS LIST FOR 500A (SPINDLE ADAPTER)

1. 65881 Adapter-Spindle
2. 65497 Washer (2)
3. 09622 Nut



SIoux
TOOLS INC.

2901 FLOYD BOULEVARD ■ PO BOX 507 ■ SIOUX CITY, IOWA 51102-0507 ■