
Genur Ingersoll-Rand Replacement Parts

150LFG-TK1 TUNE-UP KIT



This GENUINE Ingersoll-Rand Tune-up Kit contains the following parts:

	PART NUMBER	PART NAME (Description)	QTY
	10BM-25	Bearing Ejecting Washer (threaded washer)	1
	G57-729	Rear Rotor Bearing (snap ring)	1
+	150LFG-25	Rear Rotor Bearing (5/8" x 1-7/8" shielded bearing contains special lubricant)	1
+	150LFG-24	Front Rotor Bearing (3/4" x 2-1/16" shielded bearing contains special lubricant)	1
	150LF-283	Motor Housing Cover Gasket (perforated cork gasket)	1
	150LF-42	Vane	5
	150LF-111	End Plate Face	2
	150LF-284	Gear Case Gasket (plain cork gasket)	1
	10BM-69	Rotor Pinion Retainer ("C" ring)	1
+	150LFG-399	Drive Shaft Rear Bearing (3/4" I.D. x 1" O.D. x 5/8" lg roller bearing contains special lubricant)	1
	10BM-15	Drive Gear Thrust Washer (fiber thrust washer)	1
	10BM-610	Drive Gear Key (1/4" x 1/4" x 5/8" key)	1
	T02-33	Drive Shaft Front Bearing (3/4" x 1-7/8")	1
	150BMP-271	Drive Shaft Grease Seal (Garlock seal)	1
	ML50K-318	Drive Housing Bearing (3/4" I.D. x 1" O.D. x 3/4" lg roller bearing)	1
	150BMP-283	Gasket	2
	150BMP-284	Gasket	1
*	SMB-431	Plastic Gasket	1

^{*} Not Illustrated

+ See Form P6903 for correct disassembly and assembly of these bearings.

For further information refer to the following form.

Starter Model	150LF	150LFG
Installation and Maintenance Manual	P6904	P6904



Form K6904 Edition 4 03537396 March, 1998