




INSTRUCTIONS FOR 1965V & 1965VV SERIAL "E"

1. This tool is shipped without the brush shroud attached to the tool. The brush shroud must be attached for proper operation. To attach: Insert one side of the vacuum shroud into the brush shroud, making sure the lip on the vacuum shroud engages the groove in the brush shroud and work the brush shroud around the vacuum shroud until it snaps in place.



2. Do not rest tool on the brushes. This will cause them to bend and "Take a set" reducing pick-up efficiency. Store tool on its back when not in use.
3. DO NOT OPERATE TOOL WITHOUT VACUUM HOSE ATTACHED! Serious injury from flying debris could result!
4. Operation of this tool on certain materials and under certain conditions such as low humidity may cause a build up of static electricity in the tool. If this condition exists, attach a ground wire to the reducing bushing on the tool and attach the other end to a suitable ground. Also, the factory may be consulted for other grounding methods.

**SIOUX
TOOLS INC.**

2901 FLOYD BOULEVARD ■ PO BOX 507 ■ SIOUX CITY, IOWA 51102-0507 USA ■



⚠ WARNING



Some dust created by power sanding, sawing, grinding, drilling, and other construction activities contains chemicals known to cause cancer, birth defects or other reproductive harm.

⚠ ADVERTENCIA



El polvo generado al lijar, aserrar, afilar, taladrar y realizar otras tareas de construcción contiene sustancias químicas que podrían causar cáncer, malformaciones congénitas y otras alteraciones del aparato reproductor.

**SIOUX
TOOLS INC.**

2901 FLOYD BOULEVARD ■ PO BOX 507 ■ SIOUX CITY, IOWA 51102-0507 USA ■